



NUMBER: 08-057-05

GROUP: Vehicle Performance

DATE: October 27, 2005

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THE StarSCAN® FLASH FILES FOR THIS BULLETIN ARE AVAILABLE VIA THE INTERNET.

THE FLASH FILE WILL BE AVAILABLE ON THE NEXT StarSCAN® UPDATE CD RECEIVED AFTER CD 6.04.

SUBJECT:

Instrument Cluster EVIC - 12,000 Km / 7,500 Mi Service Interval Added

OVERVIEW:

This bulletin involves selectively erasing and reprogramming the instrument cluster / Cabin Compartment Node (CCN) with new software.

MODELS:

2005 (WH) Grand Cherokee (International Markets)

NOTE: This bulletin applies to vehicles equipped with a 4.7L or a 5.7L engine (sales code EVA or EZB respectively), and built prior to October 10, 2005 (MDH 1010XX).

SYMPTOM/CONDITION:

The customer may not be able to select, in the Electronic Vehicle Information Center (EVIC), a service interval of 12,000 kilometers (7,500 miles). Though a Schedule A service interval of 12,000 Km (7,500 mile) is allowed on international vehicles equipped with a gasoline powered engine, the 12,000 Km (7,500 mile) service interval was not an available service interval option in the EVIC.

New instrument cluster CCN software adds the 12,000 Km (7,500 mile) service interval option to the Service Interval section of the EVIC.

DIAGNOSIS:

Using a Scan Tool (StarSCAN®) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all engine systems are functioning as designed. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

Verify the current software version level of the CCN.

If the current CCN version level is NOT either 05.13.00 or 05.14.00, and the vehicle



operator describes or experiences the Symptom/Condition, then perform the Repair Procedure.

NOTE: There are two methods to download flash files to StarSCAN®. The first (preferred) method is to download the flash files to the StarSCAN® from the internet. The second method is to download the flash files from the StarSCAN® Software Update CD.

SPECIAL TOOLS / EQUIPMENT REQUIRED:

NPN	Battery Charger
CH9401	StarSCAN® Tool
CH9404	StarSCAN® Vehicle Cable
CH9409	StarSCAN® Documentation Kit
CH9410	StarSCAN® Ethernet Cable, 12 ft.
CH9412	StarSCAN® Software Update Device Kit
	TechCONNECT PC or equivalent
	Latest StarSCAN® Software Update CD

REPAIR PROCEDURE - USING THE INTERNET TO RETRIEVE THE FLASH FILE:

NOTE: The StarSCAN® must be at version 5.02 or higher before the "Using The Internet To Retrieve The Flash File" repair procedure can be performed.

NOTE: The StarSCAN® diagnostic scan tool fully supports Internet connectivity. However, in order to take advantage of this feature you must first configure the StarSCAN® for your dealership's network. For instruction on setting up your StarSCAN® for the dealer's network; refer to the StarSCAN® Quick Start Networking Guide available on the www.dcctools.com website under the "download center".

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Open the hood, install a battery charger and verify that the charging rate provides approximately 13.5 volts.
2. Connect the CH9410 StarSCAN® ethernet cable to the StarSCAN® and the dealer's network drop.
3. Connect the CH9404 StarSCAN® vehicle cable to the StarSCAN® and the vehicle.
4. Power ON the StarSCAN®.
5. Retrieve the old ECU (CCN) part number. Using the StarSCAN® at the "Home" screen:
 - a. Select "ECU View"
 - b. Touch the screen to highlight the appropriate ECU (CCN) in the list of modules.
 - c. Record the "Part Number", displayed on the "ECU Overview" screen, for later reference.

6. Download the flash file from the internet to the StarSCAN®. Using the StarSCAN® at the “ECU Overview” screen:
 - a. Select “More Options”
 - b. Select “ECU Flash”.
 - c. Select “Browse for New File”. Follow the on screen instructions.
 - d. Select “Download to Scantool”.
 - e. Select “Close” after the download is complete, then select “Back”.
 - f. Highlight the listed calibration.
 - g. Select “Update Controller”.
 - h. When the CCN update is complete, select “OK”.

NOTE: Due to the CCN programming procedure, a DTC may be set in other modules (TCM, BCM, MIC, SKREEM, etc.) within the vehicle, if so equipped. Some DTC's may cause the MIL to illuminate. From the “Home” screen select “System View”. Then select “All DTCs”. Press “Clear All Stored DTCs” if there are any DTCs shown on the list.

REPAIR PROCEDURE - USING SOFTWARE UPDATE CD TO RETRIEVE THE FLASH FILE:

NOTE: Before flashing this module, make sure the StarSCAN® is operating at 5.02 or later.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

NOTE: For detailed information on the operation of the StarSCAN®, refer to the Quick Reference documentation provided in the StarSCAN® documentation kit. In addition, more recent information may also be available at the www.dcctools.com website. Look under "Training Aids" and also under "Download Center > Frequently Asked Questions" for more help.

1. Open the hood, install a battery charger and verify that the charging rate provides approximately 13.5 volts.
2. Connect the CH9404 StarSCAN® vehicle cable to the StarSCAN® and the vehicle.
3. Power ON the StarSCAN®.
4. Retrieve the old ECU (CCN) part number. Using the StarSCAN® at the “Home” screen:
 - a. Select “ECU View”
 - b. Touch the screen to highlight the appropriate ECU (CCN) in the list of modules.
 - c. Record the "Part Number", displayed on the "ECU Overview" screen, for later reference.
5. Insert the StarSCAN® Software Update CD into the TechCONNECT or equivalent PC. The StarSCAN® Software Update CD will start automatically. Select “Download Flash Updates”.
6. At the **“Select a method for looking up controller flash updates.”** screen:
 - a. Select “Enter part number”. Enter the “Part Number” recorded in [Step #4](#) when prompted to do so.
 - b. Using the mouse highlight the appropriate “Calibration”. Select “Next”.
 - c. Follow the on screen instructions.
 - d. When completed, proceed to [Step #7](#).

7. With the StarSCAN® powered OFF, connect the USB Key and Gender Changer to the StarSCAN® USB port (Fig. 1).




Fig. 1 USB KEY, GENDER CHANGER, AND StarSCAN® TOOL

- 1 - StarSCAN® TOOL
 2 - GENDER CHANGER
 3 - USB KEY

-
8. Connect the StarSCAN® to the vehicle (if not already connected).
 9. Power ON the StarSCAN®.
 10. Download the flash file from the USB key to the StarSCAN®. Using the StarSCAN® at the “Home” screen:
 a. Select “Flash Download”, then select “Retrieve files from the USB storage device”
 b. Highlight the appropriate calibration. Select “Download to Scan Tool”
 c. When the download is complete, select “Close” and “Back”.
 11. Reprogram the ECU (CCN). Using the StarSCAN® at the “Home” screen:
 a. Select “ECU View”.
 b. Select “More Options”.
 c. Select “ECU Flash”.
 d. Highlight the appropriate calibration.
 e. Select “Update Controller”. Follow the on screen instructions.
 f. When the CCN update is complete, select “OK”.

NOTE: Due to the CCN programming procedure, a DTC may be set in other modules (TCM, BCM, MIC, SKREEM, etc.) within the vehicle, if so equipped. Some DTC's may cause the MIL to illuminate. From the “Home” screen select “System View”. Then select “All DTCs”. Press “Clear All Stored DTCs” if there are any DTCs shown on the list.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-45-10-95	Reprogram Instrument Cluster Cabin Compartment Node	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------