



NUMBER: 08-030-05

GROUP: Electrical

DATE: June 10, 2005

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Front Control Module - Disable RKE Horn Chirp Feature If FCM Is Replaced

OVERVIEW:

This bulletin involves disabling the Remote Keyless Entry (RKE) horn chirp feature in a replacement Front Control Module (FCM).

MODELS:

2005 (WH) Grand Cherokee (International Markets)

DISCUSSION:

In some regions and/or cities of certain international market sales areas, the sounding of a vehicle horn may not be allowed or its use may be limited (regulated).

A service replacement Front Control Module (FCM) is supplied to the dealer with the Remote Keyless Entry (RKE) horn chirp feature turned on (enabled).

If the FCM is replaced, in a vehicle that is operated in a region where the sounding of the vehicle horn is regulated, then the RKE horn chirp feature should be disabled prior to returning the vehicle to the customer.

To disable the RKE Horn Chirp feature:

- From the StarSCAN access the FCM menu.
- Select "Miscellaneous".
- Select "Sound Horn On Lock".
- Select "Disable".
- Verify that status is Disable.
- Disconnect StarSCAN from vehicle.
- Perform a RKE Lock and verify that the vehicle horn does not sound.

POLICY:

Information Only



Stick with the Specialists™