



NUMBER: 05-002-07 REV. A

GROUP: Brakes

DATE: July 13, 2007

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 05-002-07, DATED MAY 16, 2007. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ADDITIONAL MODEL AND NOTE.**

SUBJECT:

Rear Brake Squeal

OVERVIEW:

This bulletin involves replacing the rear brake pads.

MODELS:

2006 - 2007 (WK) Grand Cherokee SRT8
****2006 - 2007 (WH) Grand Cherokee SRT8 (International Markets)****

SYMPTOM/CONDITION:

Rear brakes squeal when braking, most noticeable with light brake pedal application.

DIAGNOSIS:

If the vehicle operator describes the Symptom/Condition perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68034993AA	Brake Pads - Rear

REPAIR PROCEDURE:

NOTE: **Do not use the old stainless steel shims. Discard shims.******

1. Use the procedures outlined in TechCONNECT: SERVICE INFO tab /5 - Brakes/Hydraulic - Mechanical/Brake Pads - Shoes/Removal and Installation, to replace the rear brake pads.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
05-70-22-93	Pads, Disc Brake - Replace Rear (B)	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------